



No.05/DFO/NFS/CC/2024.

Dated:19-01-2024.

"Annexure-2"

The Scholars Foundation
Scholars Academy English High School,
Inner Temple English Primary School,
Chikkabidarakallu, Tumkuru road.
Bangaluru 560073.

Sir,

Sub : Issue of "Fire Safety Compliance Report" with respect to fire prevention, fire fighting and evacuation measures maintained at to "M/S. Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bengaluru-560073.

Ref : 1)No:70/DFO/NFS/FSR/2023. Dated:01-01-2024.
2)Your request letter dated: 10-01-2024

<<>>

With reference to the above cited subject, as per Ref (1) Conditional Fire Safety Recommendation was issued. to the premises "M/S. Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.Reg..

with a condition to fulfill the recommendations the same within 3 months. With reference cited (2) above, the management of "Principal "M/S. Scholars Academy English High School, Inner Temple English Primary School" had requested for the Fire safety compliance report from our department. In this regard the above addressed educational building was inspected by Me on **12-01-2024** for issue of fire safety compliance report.

Under the above circumstance the Karnataka Fire & Emergency Services Department is issuing the "Fire Safety Compliance Report" of "M/S. Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.Reg.. subject to proper maintenance of fire fighting installations in the good working conditions and arrange for 40% of staffs/ employees training within 03 months from the date of issue of this report. *This Fire Safety Compliance Report is valid for Only One Year from the date of issue and it is renewable without fail".*

Yours faithfully,

K.H. Pradeep 19/01/24
District Fire Officer

Karnataka State Fire & Emergency Services
North Fire Station, Mysore Road,
Bangalore - 560 018.

**Karnataka Fire & Emergency Services Department
Office Of the District Fire Officer
North Fire Station
Bangalore-560018.**



No. 70 /FSR/DFO/NFS/Bng/2023.

Dated: 01-01-2024.

ANNEXURE-B

“B1 & B2 – Schools up to senior secondary level and other institutions”

To,

The Scholars Foundation
Scholars Academy English High School,
Inner Temple English Primary School,
Chikkabidarakallu, Tumkuru road,
Bangaluru 560073.

Sub: Issue of “Fire safety Recommendation” with respect of fire prevention, fire fighting & evacuation measures required at Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.

Ref: 1) Your Request Letter Dated: 13-12-2023.

><><*>@*><><

With reference to the subject above cited, the premises to Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073. Was inspected by me on 14-12-2023 with respect to Fire prevention, Fire fighting and Evacuation measures to be Recommended in the above premises and has submitted the details as under.-

Details of the building / premises :-

Name and Address of the Applicant.	:	The Scholars Foundation Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.
Name and Address of the premises.	:	Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.



Name and address of the Building owner	:	The Scholars Foundation Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangaluru 560073.
Number of buildings	:	01 building
Number of floors	:	Ground and 03 Upper floors

Floor-wise details of occupancy:-

Ground floor	:	01 AV room, 01 Seminar hall, 01 Admin room, 01 Office room, 01 Store room, 02 Class rooms, 01 wash room, 01 Activity room.
1 st Floor	:	08 Class rooms, 02 Wash room, 01 Computer lab, 01 Sports room.
2 nd floor	:	09 Class rooms, 01 Staff room, 02 wash rooms.
3 rd floor	:	08 Class rooms, 02 Wash room, 01 Computer lab, 01 Science lab.
Height of the building	:	14.40 Mtrs.
Site area	:	1417.7004 Sq.mtrs
Built-up area of each floor:-		
Ground floor	:	194.34 Sq.Mtrs
1 st Floor	:	194.34 Sq.Mtrs
2 nd floor	:	194.34 Sq.Mtrs
3 rd floor	:	194.34 Sq.Mtrs
4 th floor	:	194.34 Sq.Mtrs
Total built-up area	:	971.70 Sq.Mtrs

1. Surrounding properties:-

South (Front)	:	04 mtrs wide 9 th Cross road.
North (Rear)	:	Sri Ram School.
East (Side)	:	Private properties
west (Side)	:	Private properties

2. Set-back area available around the building :-

South (Front)	:	Direct entry form 9 th Cross road
North (Rear)	:	Nil
East (Side)	:	Nil
west (Side)	:	Nil

B. On inspection of this Educational premises, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-



Sl. No. (1)	Details (02)	Existing (03)	Recommendations (04)
01.	Accessibility to the premises	The premise is abutting 04 mtrs wide 9 th Cross road located on Southern side of the Road is hardened to Carry weight of 45,000 kgs.	The Requirement is Complied With.
02.	No. of entrances	01 entrances/exits have been provided. 03.30 mtrs width entry from Southern side of the Building.	The Requirement is complied With.
03	Diesel Generators	40 KVA one diesel generator Has been provided and connected to provide alternate power supply for staircase lighting, corridor lighting etc. In case of failure of power supply in the building.	The Requirement is complied With.
4	No. of staircases Available	Nos. of staircases : 01 no	The Requirement is complied With.
Width of staircases : 01.20 Mtrs			
Width of treads : 30 Cm's			
Height of risers : 15 Cm's			
Nos. of riser per flight : 12 No's			
Height of handrails : .90 mtrs.			
Head room clearance : 02.30 mtrs			
05.	No. lifts and capacity.	Not required	Not required
06.	Fire extinguisher	01 No CO2 type fire extinguisher of 4.5 kg capacity has been provided near each electrical panel board, electrical room.	Complied



		10 ABC type fire extinguisher of 02 kg capacity, available within 100 Square Meter Radius.	
07.	First aid Hose reel hose.	01 no's Hose Reel Hose Have been provided near the staircases and center lobby at each floor. Hose Reel Hose of 19 mm size of adequate length to reach the farthest point of floor should be provided a shut off branch having a nozzle of 5 mm size. Hose reel hoses of each floor Have been connected to overhead tank of minimum 10,000 liters capacity.	Complied
08.	At the terrace tank level with minimum pressure of 3.5 kg/cm ² .	Provide One electrically driven pump capable of delivering 450 liters of water per minute at 0.3n/mm ² pressure. The impeller of the pumps have been of bronze.	Complied
09.	Terrace tank over respective tower terrace.	02 overhead tanks of 5,000 liter capacity are provided.	Complied
10.	Escape routes	Marked on the each floor visibly to guide the students /staff make to safer places.	Displayed
11.	Fire order	Displayed on the Fire order boards indicating with the action to be taken by the employees/students in case of fire has been displayed inside the building. The notice boards have been written in Kannada and English with telephone numbers of 080-22971500, 550, 600. fire emergency 101, & 112 and telephone numbers of nearest Ambulance service,	Displayed



		Police station Management displayed.	
2.	No Smoking board	COPTPA Sec-4 direction No smoking area smoking here is an offence board have been written in English & Kannada both language have been prominently displayed at inside the entry/ exit of the each floor & Outside the school compound wall.	Displayed
3.	Fire Siren	Not provided	A fire siren shall be provided in the premises to inform staffs and children's evacuate the area in case of fire emergency.
4.	Fire fighting training	Not Trained	40% of the Occupants /Employees should be got trained in fire prevention & fire fighting at the R.A. Mundkur Fire and Emergency Services Academy, Bannerughatta Road, Bangalore-560029 regarding the maintenance of the fire prevention and fire fighting measures suggested above.
15.	Fire precaution measures :-	<p>A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.</p> <p>B. Accumulation of combustible waste in and around the premises should be avoided.</p> <p>C. The exit ways shall be always kept clear without any obstruction.</p> <p>D. Liquefied petroleum gas (LPG) should be not stored in the building.</p> <p>E. The doors shall not be kept locked/latched during working hours and shall be free from obstruction.</p> <p>F. During the class hours the class room doors shall not be locked from inside to outside.</p> <p>G. As per Hon'ble Supreme Court order all teacher and staff shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe</p>	



~ 6 ~

the Fire Safety day on April 14th of every year by conducting fire safety drills with co-ordinate with Fire Service Department.

From the above details it is clear that the applicant shall adopt all necessary fire prevention and fire fighting measures in the building. In Issue of "Fire Safety Recommendation" for Low Rise Educational Building at *M/R Scholars Academy English High School, Inner Temple English Primary School, Chikkabidarakallu, Tumkuru road, Bangalore 560073*. This Fire Safety Recommendation report is valid for a period of only one year from the date of issue and is Renewable.

• All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.4 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully

K.H. Prasanna 01/01/2020
District Fire Officer
Karnataka State Fire & Emergency Services
North Fire Station, Mysore Road,
Bangalore - 560 018.